Exhibit F

ETHICO N.INC.

·a Johnson-Johnson company P.O. BOX 151 SOMERVILLE • NEW JERSEY • 08878-0151

October 15, 1992

cc: B. Matlaga J. McDivitt A. Melveger RDCF

Mark Cafone

SEVEN YEAR DATA FOR TEN YEAR PROLENE STUDY: ERF 85-219

This report contains a summary of IR, IV, GPC, OM and SEM data supporting this study.

IR and IR Microspectroscopy (D.Burkley)

IR examinations were done for all explants at all sites to verify the suture identity for each explant. For all explanted sutures recovered from all 6 sites for every dog in this study, IR data showed each suture to be correctly identified.

IR microspectroscopy was used to examine cracked areas in ETHILON, Novafil and PROLENE $^{\text{\tiny{N}}}$ explants. IR spectra obtained for cracked PROLENE specimens (Figure A) showed possible evidence of slight oxidation (a broadened weak absorbance at about 1650 cm-1). spectra obtained for cracked areas of ETHILON and Novafil did not differ from uncracked areas (Figures B and C), but expected IR absorbances for oxidation would be masked by the strong carbonyl absorbances normally observed for these sutures. Figures D and E show pictures of the areas examined by IR microspectroscopy for ETHILON and Novafil.

IV and GPC (E.Muse)


Gel Permeation Chromatography (GPC) was run on PROLENE sutures explanted from dogs after seven years. The GPC data was compared to data from a current 4/0 PROLENE suture. The results indicate that there was no significant difference in molecular weight between the 4/0 PROLENE control and the seven year explants.

The following PROLENE explant samples were analyzed:

Dog 1995 - site 3 (SR33853)

Dog 2007 - sites 1 and 6 (SR34003) Dog 2008 - site 2 (SR34066) Dog 2019 - sites 2 and 3 (SR34180)

The GPC analysis was run on the Waters 150C GPC at 140°C using 1,2,4 trichlorobenzene as a mobile phase with Waters GPC columns. The instrument was calibrated with polypropylene standards.



Page 2

Inherent Viscosity (IV) was determined on ETHILON^M and Novafil sutures explanted from dogs after seven years. The IV data was compared to IV data from one and two year explants. The following results were found:

- No significant differences were seen in IV values after one and two years.
- 2) Seven year IV values ranged from 75% to 93% of the one and two year IV values for ETHILON sutures.
- 3) Seven year IV values ranged from 75% to 90% of the one and two year values for Novafil.

The dog explant samples examined were from duplicate sites on four dogs for each time period (one, two and seven years). The IV data was determined using concentrations of 0.1 dl/g with HFIP as a solvent at 25°C.

OPTICAL MICROSCOPY and SCANNING ELECTRON MICROSCOPY (E.Lindemann)

Conclusions

- The 7 year in-vivo results generally substantiated the five year findings. They also closely correspond to the observations of explanted sutures from the dog that died prematurely after 6 years and 10.5 month implantation time.
- Degradation in PROLENE is still increasing and PVDF, even though a few cracks were found, is still by far the most surface resistant in- house made suture in terms of cracking.
- Of the eight explanted ETHILON sutures all showed heavy cracking and, in many cases, abrasion of the dyed surface layer. A decrease in the suture diameter was apparent in several cases.
- Cracks were not found in the seven Novafil explants. However a few longitudinal scratches probably due to mechanical damage and one longitudinal crack were observed.

Introduction

In November 1985 twenty-four dogs had been implanted with sets of ETHILON, PROLENE, PVDF and Novafil sutures for a ten year study. In 1990, after five years, explants from 5 beagle dogs were described in " TEN YEAR IN-VIVO STUDY SCANNING ELECTRON MICROSCOPY FIVE YEAR REPORT" by Elke Lindemann. The next explantation, after 7 years, was to start in June 1992. However, after 6 years and 10.5 months dog #1995 died prematurely. The microscopical examination of those explants was described in " TEN YEAR IN-VIVO STUDY: SCANNING ELECTRON AND LIGHT MICROSCOPY INTERIM REPORT ON DOG #1995 AFTER 6 YEARS, 10.5 MONTH, SR# 33788 and are included in the conclusion section of this report. In June of 1992 after 7 years, sutures were explanted from another set of 4 dogs. This report presents the results of the light and scanning electron microscopical examination of those explants.

¹SR33853, SR34003, SR34066, SR34180

Page 3

Experimental

Four dogs had been implanted in November 1985 with the following 5-0 sutures:

	Site 1	Site 2	Site 3	Site 4	Site 5	Site 6	
Dog 2001	PVDF	ETHILON	Novafil	PROLENE	PROLENE	Novafil	
Dog 2007	PROLENE	Novafil	ETHILON	PVDF	PVDF	PROLENE	
Dog. 2019	Novafil	PROLENE	PROLENE	PVDF	ETHILON	ETHILON	
Dog 2008	ETHILON	PROLENE	Novafil	PVDF	ETHILON	. PVDF	

Starting in June of this year the above dogs were sacrificed in weekly intervals. Approximately 20cm long sections of the explanted sutures were received in microscopy in glass vials which were kept refrigerated until they were examined.

Also the explanted LC 100 clip with about 2cm of each suture bundle was delivered in the same vial. The clip and the attached sutures were still deeply embedded in the surrounding tissue. These 'not cleaned' sutures were supposed to answer the question whether the process of cleaning and tissue removal might be responsible for an observed cracking. The primary concern of this study was however to examine the long pieces of explanted suture. Most of these specimens were still surrounded with some tissue, fortunately at a level low enough not to obscure examination in the light microscope under transmitted light. It was possible to examine the embedded PROLENE suture where the cracking of the suture was seen through the tissue. For this reason and time constrains the clip-attached sutures were not examined at this time.

To show that the drying and coating with a metal under vacuum, necessary for SEM examination, did not introduce cracking and other surface defects each strand of each long suture was 100% inspected in the Olympus Light Microscope in water. Oil, the usual medium for light microscopical inspection, was not chosen for this examination in order to eliminate surface changes during sample preparation. To cut down on lensing effects of the curved suture, the samples were photographed in polarized light using a 10x phase condenser with an ordinary transmitted light 20x objective (a 20x phase condenser was not available). The light diffraction introduced by the phase condenser was enough to allow an easier focusing at the focal plane of the largest diameter. Photomicrographs were prepared at 285x of areas which showed surface changes.

Strands of the suture including the above areas were then prepared for SEM observation in the JEOL JSM 840 AII by coating them under vacuum with gold to provide an electron conductive surface. Photomicrographs were prepared at 500x magnification.

Page 4

Results

1) LM and SEM of PROLENE suture explants from seven implantation site.

In Figure 1A through 1D one area per site from each of the four dogs is shown in transmitted light. Out of seven sites cracking was found on PROLENE sutures from three sites. Notice the cracks observable through the still adhering tissue in Figure 1A in the suture from site 2.

In Figure 1 and 2 SEM views of areas are shown after most of the tissue had been carefully removed. Again out of seven sites sutures from three sites had areas which showed cracking.

2) LM and SEM of ETHILON suture explants from six implantation sites.

In Figure 3A through 3C sutures are shown from six different sites. Transmitted light allowed visualization of the differences between the intact dyed surface layer and the underlying colorless layers of the suture. In Figure 3A site 5 and Figure 3C site 3 the colorless area had not only lost its dyed surface layer but was abraded to such a degree that a decrease in suture diameter was found.

In Figures 3 and 4 the cracking and abrasion on sutures from all six sites, as observed with the SEM, is shown. Here also the decrease in diameter is particularly dramatic in Figure 3 site 1.

3) LM and SEM of PVDF suture explants from six implantation sites.

Figure 5A through 5C show six sites of PVDF explants as seen with the light microscope. Notice the intact surface on all the sutures.

In Figures 5 and 6 the SEM examination of the PVDF sutures is shown. Only on the suture from one site (Figure 6 site 6) some cracks are found. The surfaces of the sutures from the other five sites show some striations which could be mechanical damage, otherwise the surfaces look intact. The contaminant on the site 4 (Figure 5) suture is tissue which had not been removed completely.

4) LM and SEM of Novafil suture explants from five implantation sites.

Figure 7A through 7C show the Novafil sutures as observed with the light microscope. All surfaces from all sites look undamaged. Figure 7 and 8 show the SEM examination of these sutures. A few longitudinal scratches and cracks were found, see sites 1,2,3 (Figure 7,8). Also on the site 2 suture (Figure 8) still adhering tissue is found.

5) Degradation dependency on implantation site

To probe the question as to whether one implantation site might be more or less stressful towards the suture, a comparison was made of the six sites.

Page 5

	Site 1	Site 2	Site 3	Site 4	Site 5	Site 6
Dog 1995	ETHILON cracks	PVDF	PROLENE cracks	Novafil	Novafil cracks	ETHILON cracks
Dog 2001	PVDF	ETHILON cracks	Novafil	PROLENE	PROLENE cracks	Novafil
Dog 2007	PROLENE	Novafil scratch	ETHILON cracks	PVDF	PVDF	PROLENÉ cracks
Dog 2019	Novafil scratch	PROLENE	PROLENE	PVDF	ETHILON Cracks	ETHILON cracks
Dog 2008	ETHILON .	PROLENE cracks	Novafil cracks	PVDF	ETHILON cracks	PVDF cracks

The only site, in the 5 dogs of this study, from which sutures were explanted that showed no surface damage was site 4. However, of those five sutures three were PVDF and one was Novafil. Those are the sutures that showed only marginal surface changes in this study. Therefore this observation can be discounted.

moun

Elke Lindemann

Eugene P. Muse

Daniel F. Burkley

Attachment

4 7YEAR.DFB

92 1471

ETHICON,INC.

a Johnson Johnson company

P.O. BOX 181

BOMERVILLE - NEW JERSEY - 08878-0181

October 19, 1992

To: Mr. Mark A. Cofone

cc: Mr. Chao Chen
Mr. John Karl
Mr. Robert Lilenfeld
Ms. Barbara Matlaga
Ms. Irene Nozad
RDCF

Interim report on the physical testing of PROLENE, PVDF, ETHILON & NOVAFIL after seven year subcutaneous implantation in the Beagle Dogs - TEN YEAR BSR STUDY, ST#E211-92, 85-219

Attached table shows the physical properties of explanted and baseline samples of size 5-0 Ethilon, Novafil, Prolene and PVDF (N) sutures up to the seven year mark of the ten year BSR study. Implanted Ethilon shows a decrease in breaking strength of 37% at the seven year period compared to the baseline samples. Ethilon samples looked fragile and worn out with spotted surface. Novafil samples show a corresponding decrease of 14% in breaking strength while Prolene and PVDF show no significant change after seven year of implantation. There is a large variation in the elongation results of these samples and all of them showed an increase in the elongation. Young's Modulus values showed a decreasing trend in the range of 50-70% for all the sutures through the seven year period.

Seven year testing conditions were based on the one year and two year data to keep them consistent throughout the study. Tensile testing conditions were 1 in./min crosshead speed (XH) for the Prolene samples and 5 in./min for all other samples with gauge length (G.L.) of 1 inch. If you have any further questions, please feel free to contact me at x2205.

VAfamus Vishvaroop Agarwal


Reference: Two year tensile data report from Dr. Peter Moy to Dr. Glenn Graves "10 Year Prolene BSR Study", August 18, 1988.
b:10YR-REP

OCT 93 1992

RD-CENTRAL FILE

CONFIDENTIAL SUBJECT TO STIPULATION AND ORDER OF CONFIDENTIALITY

Figure A - Comparison IR Spectra of Cracked and Non-cracked Regions of PROLENE (SR33788)



TEN YEAR PROLENE BSR STUDY 7-YEAR DATA SUMMARY

Suture	Dog	Site	Straight Strength Elongation		Modulus	
		•	(lb)	(%)	(psi)	
ETHILON	2001	2 5	1.92 ± 0.03	49.50 ± 3.81	263500 ± 20360	
ETHILON*	2008	5	0.89 ± 0.16	25.14 ± 4.10	· 181500 ± 8866	
ETHILON*	2008	1	0.64 ± 0.261	$\cdot 20.73 \pm 6.72$	149300 ± 25230	
ETHILON	2019	5	1.63 ± 0.12	40.12 ± 4.77	298600 ± 47810	
ETHILON	2019	. б	1.65 ± 0.25	35.76 ± 12.21	244200 ± 12310	
Average			1.35	34.25	227420	
NOVAFIL	2001	3	1.53 ± 0.14	60.80 ± 3.54	166900 ± 13150	
NOVAFIL	2001	б	1.53 ± 0.02	59.20 ± 2.26	182100 ± 13130	
NOVAFIL	2007	. 2	· 1.49 ± 0.01	56.80 ± 2.38	$.177000 \pm 7476$	
NOVAFIL	2008	3	1.51 ± 0.02	57.88 ± 3.62	167400 ± 8933	
NOVAFIL	2019	1	1.51 ± 0.02	54.60 ± 1.54	191100 ± 4925	
Average .			1.51	57.86	176900	
PROLENE	2001	. 4	1.58 ± 0.05	80.14 ± 8.15	207700 ± 14672	
PROLENE	2001	5	1.61 ± 0.03	80.26 ± 2.07	219600 ± 19430	
PROLENE	2007	6	1.62 ± 0.02	79.50 ± 6.41	218925 ± 18508	
PROLENE	2007	1	1.61 ± 0.04	76.76 ± 11.63	$\cdot 217275 \pm 20455$	
PROLENE	2008	2	1.54 ± 0.02	70.76 ± 10.21	220000 ± 8305	
PROLENE	2019	2	1.61 ± 0.03	78.06 ± 12.46	203125 ± 19402	
Average	J		1.60 .	77.58	214438	
PVDF (N)	2001	1	2.14 ± 0.04	67.66 ± 2.92	163900 ± 8454	
PVDF (N)	2007	4	2.13 ± 0.04	67.62 ± 2.56	167600 ± 13220	
PVDF (N)	2007	5	2.19 ± 0.06	61.80 ± 1.03	188125 ± 2634	
PVDF (N)	2008	4	1.86 ± 0.08	84.80 ± 15.29	131800 ± 11150	
PVDF (N)	2019	-4	2.13 ± 0.06	64.72 ± 3.04	167000 ± 5115	
Average			2.09	69.32	163685	

^{*} Looked Worn Out

Untested:

Conditions: Tested on Instron 4201 (Series IX) at G.L. of $\dot{1}$ in, and XH Speed of 1"/min for Prolene and 5"/min for all other samples.

ST# E211-92,85-219

b:\7yr-bsr

⁽i) PVDF in Dog#2008 at Site#6 had less than required gage length.

⁽ii) Ethilon in Dog#2007 at Site#3 looked very fragile, spotted surface and worn out.

DATA SUMMARY OF TEN YEAR PROLENE BSR STUDY

	TIME PERIOD (Years)				CHANGE FROM BASELINE (%)		
	0	1	2	` 7	1	. 2	7
BREAKING STRENGTH (lb)						-	
ETHILON	2.13	. 1.76	1.75	1.35	-17	-18	-37
NOVAFIL	1.76	1.68	1.64	1:51	-5	-7	-14
PROLENE	1.68	1.56	1.64	1.60	-7	-2	5
PVDF(Ņ) ·	2.17	2.12	2.16	2.09	-2	0	· -4
		27					
ELONGATION (%)				•		•	
ETHILON	27	29	25	34	7	7	26
NOVAFIL	. 37	41	32.	58	11	_14	57
PROLENE	37	37	33	78.	0	· -11	111
PVDF(N)	34	41	′ 38	· 69	21	12	103
YOUNG'S MODULUS (Kpsi)	-					,	
ETHILON	544	352	449	227	-35	-17	58
NOVAFIL -	369	314	301	177	-15	-18	-52
PROLENE	721	661	677	214	-8	-6	-70
PVDF(N)	330	306	392	164	-7	19	-50

Testing Conditions: G.L. = 1 in. and XH Speed = 1"/min for Prolene and 5"/min for all other samples.

ST# E211-92, 85-219 B:\10YR-SUM